



Government of West Bengal
Office of the Director General
West Bengal Fire & Emergency Services
13D, Mirza Ghalib Street, Kolkata - 16

Memo No.:FSR/0125186211200256

Date : 24-06-2024

From :
Director
Fire Prevention Wing,
West Bengal Fire & Emergency Services

To :
New Vista Academy
Mouza - Shibrapore, Ashuti - II Gram Panchayet., P.S. -Maheshtala. Dist - South 24 Parganas. PIN - 700141

Sub : Partial Fire Safety Certificate for Ground and 1st. Floor of G +III storied under Group Educational building in the name and style "New Vista Academy" at the premises No. Mouza -Sibrapore, Ashuti -II Gram Panchayet.P.S.- Maheshtala. Dist.- South 24 Parganas, Pin - 700141.

This is in reference to your AIN 211892406300000350 dated 03-May-2024 regarding Partial Fire Safety Certificate for Ground and 1st. Floor of G +III storied under Group Educational building in the name and style "New Vista Academy" at the premises No. Mouza -Sibrapore, Ashuti -II Gram Panchayet.P.S.- Maheshtala. Dist.- South 24 Parganas, Pin - 700141.

The performance of the Fire Fighting System as incorporated in the building were tested at random and found satisfactorily working condition. In view of the above this office is releasing the **Fire Safety Certificate** for occupancy of the aforesaid building.

Recommendation:

This Part Fire Safety Certificate is issued with a condition to provide wet riser cum downcomer system with Main Fire Pump &



The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892406300000350

For NEW VISTA ACADEMY

Principal

NEW VISTA ACADEMY

Secretary

stand by pump of 1620 LPM, Jockey Pump of 180 LPM at Ground Floor level, connected to dedicated Fire Water Reservoir of 50000 Ltrs, complied with the existing down comer system from OHWR of 25000 Ltrs through Terrace Pump.

1. Driveway must be free of any type of obstruction for easy movement of Fire Appliances. No parking will be allowed on the Drive way.
2. Entrances / Exits as marked in the sanctioned plan drawing must be opened and free from any type of obstruction.
3. The Fire license for the LPG bank shall be renewed as per norms.
4. To eliminate risk of Fire Hazards, Good House Keeping both for insides and outside of the building shall be strictly maintained.
5. Existing Electrical wiring of the whole building shall have to be carefully checked for any wear and tear in them, particularly lines above false ceiling & ducts.
6. A fire control room including a closed circuit TV system shall have to be installed which observe all the floors of the building.
7. The notice of Fire Fighting and Evacuation from the building shall be prepared and displayed at all vulnerable places of the Building.
8. The employees and security staff shall be conversant with installed fire fighting equipments of the building and to operate in the event of fire and testing.
9. Mock fire practice and evacuation drill shall be performed periodically with participants of all the occupants of the building.
10. Transformer and Switch Gears room shall be protected with automatic CO₂ or DCP Fire extinguishers confirming I.S. specifications.



The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892406300000350

For NEW VISTA ACADEMY

Raj
Principal

NEW VISTA ACADEMY

[Signature]
Secretary

round the clock for fire safety of the building.

12. First Aid fire fighting system shall be provided as per I.S. specifications.

13. Arrangement shall have to be made for regular checking, testing, and maintenance of all the Fire Fighting installation in the Building to keep them in perfectly good working condition at all the times.

14. Periodical flashing of water in the Hydrants and sprinklers Pipe lines shall be made to maintain the efficient working performance of above mentioned system. Another Fire Pump shall be installed as standby.

15. The Fire Safety audit to be conducted at regular interval and to be recorded in the Fire Prevention maintenance register.

16. This Partial Fire Safety Certificate is valid for three years and has to be renewed every completion of three years from the date of issue of this letter and Fire Safety Certificate shall be obtained after completion of building.

17. A certificate is to be obtained from the Director General, West Bengal Fire & Emergency Services regarding performance of all the Fire Safety arrangements and installations of the building.

Valid Upto : 23-Jun-2027



Signature valid

Digitally Signed
Name: ABHINAV PRADHEY
Date: 24-Jul-2024 13:14:12
Reason: D-Sign
Location: E-Dist 2.0

Director

West Bengal Fire & Emergency Services

The authenticity of this document can be verified by accessing the URL: edistrict.wb.gov.in and then clicking on the Verification of Digitally Signed Document link and keying in the Unique Number : 211892406300000350

For NEW VISTA ACADEMY


Principal

NEW VISTA ACADEMY

Secretary