Annexure D

BUILDING SAFETY CERTIFICATE

No.: 1876/G-9 It is certified that the exis	ting building NI	EW VISTA AC	ADEMY SARDA of the		d: 19/06/2024.	
building or premises) at KOLKATA-700141 (a	NATUNHAT,	SHIBRAMPO	ORE, BIREN R			
Detail of Block(o) in	Block	Block	Block	Block	Block	Block

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	1st Floor & 2nd Floor	1st Floor & 2nd Floor				

- 1. No Addition / Alteration be made in the existing building
- 2. The staircase should be clear from any obstacle
- 3. Every year the inside and outside to be painted by the school authority
- 4. On regular basis the cracks on the wall and other parts to be mending properly and taken care by the school authority

Issued on ...19/06/2024... at ... Sarada Park Notunhat... by PWD Assistant Engineer

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

W VISTA ACADEMY principal

T



Designation :

Name & Address of Department/ Office:

NEW VISTA CADEMY